



Go to VARIAC.com to purchase and for technical support. Made in the USA






MOTOR CIRCUIT
120V, 50/60 HZ
* ROTATION AS VIEWED
FROM MOTOR END
MOTOR SPEED: SEE CHART

SPEED (SECONDS)	MODEL NUMBER	DIM "A"
5	5M2510-3 +	21.23 [539.2]
15	15M2510-3 +	21.23 [539.2]
30	30M2510-3 +	21.62 [549.1]
60	60M2510-3 +	21.62 [549.1]

SPECIFICATIONS INPUT OUTPUT TERMINAL CONNECTIONS SHAFT FOR INCREASING VOLTAGE CONSTANT CONSTANT ROTATION CURRENT **IMPEDANCE** AS VIEWED TO VOLTS | HERTZ | VOLTS WIRING LOAD LOAD FROM BASE END NCREASE MAX. MAX. MAX. MAX. VOLTAGE AMPS AMPS KVA KVA JUMPER ■ OUTPUT 4-4-4 3-3-3 CW 2-2-2 50/60 0-240 25 10.40 30 12.5 CCW 4-4-4 3-3-3 240 PHASE CW 4-4-4 3-3-3 WYE 25 60 0-280 12.10 π 5-5-5 4-4-4 3-3-3 CCW CW 2-2-2 4-4-4 4-D SINGLE 0-120 75 9.00 90 10.8 2-2-2 4-4-4 CCW 2-D PHASE 120 50/60 CW 1-1-1 4-4-4 PARALLEI 75 10.50 0-140 XX 2-2-2 5-5-5



NOTES:

TI IF GANGED UNITS ARE USED IN A SYSTEM THAT ORDINARILY HAS A COMMON NEUTRAL OR GROUND BETWEEN SOURCE AND LOAD, THE NEUTRAL OR GROUND MUST BE CONNECTED TO THE COMMON TERMINALS OF THE VARIABLE TRANSFORMER ASSEMBLY. IF THE SYSTEM HAS NO NEUTRAL, THE LOAD MUST BE BALANCED OR THE TRANSFORMER WILL BE DAMAGED.

XX REQUIRES THREE 51LAC PARALLELING CHOKES.

- JUMPER PROVIDED IN STANDARD COMMON POSITION AND SHOULD BE MOVED OR REMOVED AS REQUIRED.
- $+\ \mbox{MOTOR}$ driven units use terminal connections for CCW increasing voltage, as viewed from the base end.
- ++ LINE TO LINE VOLTAGE.